

1. Name of Reporting Railroad Keokuk Junction Railway [KJRY]				1a. Alphabetic Code KJRY				1b. Railroad Accident/Incident No. KJ1910180																			
2. Name of Other Railroad or Other Entity with Consist Involved				2a. Alphabetic Code				2b. Railroad Accident/Incident No.																			
3. Name of Railroad or Other Entity Responsible for Track Maintenance (single entry) Keokuk Junction Railway [KJRY]				3a. Alphabetic Code KJRY				3b. Railroad Accident/Incident No. KJ1910180																			
4. U. S. DOT Grade Crossing Identification Number				5. Date of Accident/Incident month: 1 day: 0 year: 2019				6. Time of Accident/Incident 4:25 AM <input type="checkbox"/> PM <input checked="" type="checkbox"/>																			
7. Type of Accident/ Incident (single entry in code box)				1. Derailment 2. Head on collision 3. Rear end collision				4. Side collision 5. Raking collision 6. Broken train collision				7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction				10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts				13. Other (describe in narrative) 13							
8. Cars Carrying HAZMAT N/A				9. HAZMAT Cars Damaged/ Derailed N/A				10. Cars Releasing HAZMAT N/A				11. People Evacuated N/A				12. Subdivision SYSTEM											
13. Nearest City/ Town BURNSIDE				14. Milepost (to nearest tenth) 205.4				15. State Abbr. IL				16. County HANCOCK															
17. Temperature (F) (specify if minus) 52 °F				18. Visibility (single entry) 1. Dawn 3. Dusk 2. Day 4. Dark Code 2				19. Weather (single entry) 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow Code 1				20. Type of Track 1. Main 3. Siding 2. Yard 4. Industry Code 1															
21. Track Name/ Number SINGLE MAIN LINE				22. FRA Track Class (1-9, X) X				23. Annual Track Density (gross tons in millions) 1.65				24. Time Table Direction 1. North 3. East 2. South 4. West Code 4															
25. Type of Equipment Consist (single entry)				1. Freight train 2. Passenger train-Pulling 3. Commuter train-Pulling 4. Work train				5. Single car 6. Cut of cars 7. Yard/switching 8. Light loco(s)				9. Maint./inspect. car A. Spec. MoW Equip. B. Passenger Train-Pushing C. Commuter Train-Pushing				D. EMU E. DMU Code 1				26. Was Equipment Attended? 1. Yes 2. No Code Y				27. Train Number/Symbol PREX			
28. Speed (recorded speed if available) R - Recorded E - Estimated 010 MPH				Code E				30. Type of Territory (enter codes that apply) Signalization (Mandatory) 1. Signalized 2. Not Signalized Method of Operation/Authority for Movement (Mandatory) 1. Signal Indication 2. Direct Train Control 3. Yard/Restricted Limits 4. Block Register Territory 5. Other Than Main Track Supplemental/Adjunct Codes (Mandatory*) * Mandatory to the extent that all applicable codes are entered				30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled operation 1 = Remote control portable transmitter 2 = Remote control tower operation 3 = Remote control portable transmitter - more than one remote control transmitter Code 0															
29. Trailing Tons (gross tonnage, excluding power units) 1,485				31. Principal Car/Unit (1) First involved (derailed, struck, etc) PREX003069				a. Initial and Number 002				b. Position in Train 002				c. Loaded (yes/no) N				32. If any railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 00 Drugs 00							
(2) Causing (if mechanical, cause reported) PREX003069				a. Head End 3				Mid Train b. Manual c. Remote 0 0				Rear End d. Manual e. Remote 0 0				35. Cars (Include EMU, DMU, and Cab Car Locomotives.) (1) Total in Equipment Consist 11 (2) Total Derailed 0				a. Freight 11 b. Pass. 0 c. Freight 0 d. Pass. 0 e. Caboose 0							
36. Equipment Damage This Consist \$ 17,000				37. Track, Signal, Way, & Structure Damage \$ 0				38. Primary Cause Code E79L				39. Contributing Cause Code E99L															
Number of Crew Members				Length of Time on Duty																							
40. Engineers/ Operators 1				41. Firemen 1				42. Conductors 1				43. Brakemen 1				44. Engineer/Operator Hrs: 06 Mins: 55				45. Conductor Hrs: 06 Mins: 55							
Casualties to:				46. Railroad Employees 0				47. Train Passengers 0				48. Others 0				49a. Special Study Block A OTH				49b. Special Study Block B 000-000-000							
50. Latitude 40.5027				51. Longitude -91.1064																							
52. Narrative Description (Be specific, and continue on separate sheet if necessary) PREX 3069 HAD A TURBO FAILURE CATCHING THE AIR BOX FILTERS ON FIRE, BURNING A CONNECTOR HOSE BETWEEN THE BLOCK AND TURBO. TURBO BACK FIRED INTO AIR BOX.																											
53. Typed/Printed Name & Title of Preparer				54. Signature				55. Date																			
NOTE: This report is part of the reporting railroad's accident report pursuant to the accident reports statute and, as such shall not "be admitted as evidence or used for any purpose in any suit or action for damages growing out of any matter mentioned in said report...." 49 U.S.C. 20903. See 49 C.F.R. 225.7 (b).																											
This collection of information is mandatory under 49 CFR 225, and is used by FRA to monitor national rail safety. Public reporting burden is estimated to average 2 hours per response, including the time for reviewing instructions, searching existing databases, gathering and maintaining the data needed, and completing and reviewing the collection of information. The information collected is a matter of public record, and no confidentiality is promised to any respondent. Please note that an agency may not conduct or sponsor, and a person is not required to respond to a collection of information unless it displays a currently valid OMB control number. The OMB control number for this collection is 2130-0500.																											