

1. Name of Reporting Railroad Union Pacific Railroad Company [UP]			1a. Alphabetic Code UP			1b. Railroad Accident/Incident No. 0719HL020		
2. Name of Other Railroad or Other Entity with Consist Involved			2a. Alphabetic Code			2b. Railroad Accident/Incident No.		
3. Name of Railroad or Other Entity Responsible for Track Maintenance (single entry) Union Pacific Railroad Company [UP]			3a. Alphabetic Code UP			3b. Railroad Accident/Incident No. 0719HL020		
4. U. S. DOT Grade Crossing Identification Number			5. Date of Accident/Incident month: 0 day: 7 year: 2019			6. Time of Accident/Incident 7:19 AM <input checked="" type="checkbox"/> PM <input type="checkbox"/>		
7. Type of Accident/ Incident (single entry in code box)			7. Side collision			13. Other (describe in narrative) Code 01		
8. Cars Carrying HAZMAT N/A			9. HAZMAT Cars Damaged/ Derailed N/A			10. Cars Releasing HAZMAT N/A		
11. People Evacuated N/A			12. Subdivision TRENTON SUB					
13. Nearest City/Town MERCER			14. Milepost (to nearest tenth) 380.7			15. State Code Abbr. MO 29		
16. County MERCER			17. Temperature (F) (specify if minus) 66 ° F			18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		
19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1			20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1					
21. Track Name/ Number SINGLE MAIN TRACK			22. FRA Track Class (1-9, X) 4			23. Annual Track Density (gross tons in millions) 31.20		
24. Time Table Direction Code 1. North 3. East 2. South 4. West 2			25. Type of Equipment Consist (single entry) 1. Freight train 5. Single car 9. Maint./inspect. car D. EMU 2. Passenger train-Pulling 6. Cut of cars A. Spec. MoW Equip. E. DMU 3. Commuter train-Pulling 7. Yard/switching B. Passenger Train-Pushing 4. Work train 8. Light loco(s) C. Commuter Train-Pushing			26. Was Equipment Attended? 1. Yes 2. No Code Y		
27. Train Number/Symbol MBUF			28. Speed (recorded speed if available) R - Recorded 050 MPH E - Estimated Code R			30. Type of Territory (enter codes that apply) Signalization (Mandatory) 1. Signaled 2. Not Signaled Method of Operation/Authority for Movement (Mandatory) 1. Signal Indication 2. Direct Train Control 3. Yard/Restricted Limits 4. Block Register Territory 5. Other Than Main Track Q-Traffic Control System/CTC Supplemental/Adjunct Codes (Mandatory*) * Mandatory to the extent that all applicable codes are entered		
29. Trailing Tons (gross tonnage, excluding power units) 15,045			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled operation 1 = Remote control portable transmitter 2 = Remote control tower operation 3 = Remote control portable transmitter - more than one remote control transmitter Code 0					
31. Principal Car/Unit (1) First involved (derailed, struck, etc) CRDX023307			a. Initial and Number 004			b. Position in Train 000		
(2) Causing (if mechanical, cause reported)			c. Loaded (yes/no) Y			32. If any railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs		
33. Was this consist transporting passengers? (y/n) No			34. Locomotive Units (Exclude EMU, DMU, and Cab Car Locomotives.) a. Head End (1) Total in Train 3 (2) Total Derailed 0			b. Mid Train b. Manual c. Remote 0 0		
c. Rear End d. Manual e. Remote 0 0			35. Cars (Include EMU, DMU, and Cab Car Locomotives.) a. Freight b. Pass. c. Freight d. Pass. e. Caboose (1) Total in Equipment Consist 106 (2) Total Derailed 69					
36. Equipment Damage This Consist \$ 4,395,775			37. Track, Signal, Way, & Structure Damage \$ 348,600			38. Primary Cause Code T001		
39. Contributing Cause Code			Number of Crew Members			Length of Time on Duty		
40. Engineers/ Operators 1			41. Firemen			42. Conductors 1		
43. Brakemen			44. Engineer/Operator Hrs: 04 Mins: 04			45. Conductor Hrs: 04 Mins: 04		
Casualties to:			46. Railroad Employees			47. Train Passengers		
Fatal 0			48. Others 0			49a. Special Study Block A CWR		
Nonfatal 0			49b. Special Study Block B 000-000-000					
50. Latitude 40.490455			51. Longitude -93.534965					
52. Narrative Description (Be specific, and continue on separate sheet if necessary) THE MBUFW-23 TRAVELING SOUTH ON THE TRENTON SUB AT 50MPH, DERAILED 69 LOADED SAND CARS AT MP 381. CAUSE WAS DUE TO SOFT ROADBED.								
53. Typed/Printed Name & Title of Preparer			54. Signature			55. Date		
NOTE: This report is part of the reporting railroad's accident report pursuant to the accident reports statute and, as such shall not "be admitted as evidence or used for any purpose in any suit or action for damages growing out of any matter mentioned in said report..." 49 U.S.C. 20903. See 49 C.F.R. 225.7 (b).								
This collection of information is mandatory under 49 CFR 225, and is used by FRA to monitor national rail safety. Public reporting burden is estimated to average 2 hours per response, including the time for reviewing instructions, searching existing databases, gathering and maintaining the data needed, and completing and reviewing the collection of information. The information collected is a matter of public record, and no confidentiality is promised to any respondent. Please note that an agency may not conduct or sponsor, and a person is not required to respond to a collection of information unless it displays a currently valid OMB control number. The OMB control number for this collection is 2130-0500.								